

Evaluation of role of Machining parameters on variation in Cutting forces.

Objective:


To study the effect of cutting velocity and feed on cutting forces in turning steel with uncoated carbide inserts (positive rake).

Measurement principle:

Piezo-electric dynamometer.

piezo-electricity:

Ability of some materials (mainly crystals) to generate electric potentials in response to mechanical stress. This may take the form of a discharge or separation of electric charge across the crystal lattice.



- $P_x$  = longitudinal cross force (x.m)
- $P_y$  = Radial feed force (y.m)
- $P_z$  = tangential force / main cutting force
- $P_{xy}$  = feed force

DATE . . .

SHEET NO. 2

## Experimental Conditions: →

Sl. no.	Item	Description
1.	Machine Tool	J122 HMT center lathe
2.	Work material - specification	17 Cr Ni Mo 6 / 32 NiCrMo 14.5
3.	Work material - composition	C = 0.8%
4.	Cutting tool - specification	SPUN 120308
5.	Cutting tool - geometry	$\lambda = 0, \gamma_0 = 6^\circ, \alpha_0 = 6^\circ, \alpha_n = 6^\circ, \phi_1 = 16^\circ, \phi_2 = 75^\circ$ $r = 0.18 \text{ mm}$
6.	Cutting tool - material	composite carbide (grade = P30)

Observations and results :-

By performing this experiment we have got the value of the tangential force ( $P_z$ ) and the value of  $\xi$  from 'chip morphology' experiment. (In this experiment the value of  $\xi$  is given.)

we know that,

$$P_z = t \xi \tau_s (\xi - \tan \gamma_0 + 1)$$

for orthogonal machining of ductile materials,

$$P_{xy} = t \xi \tau_s (\xi - \tan \gamma_0 - 1).$$

$$\therefore P_{xy} = \frac{P_z (\xi - \tan \gamma_0 - 1)}{(\xi - \tan \gamma_0 + 1)}$$

for orthogonal machining of ductile materials,

$P_{xy}$  makes an angle  $(\frac{\pi}{2} - \phi)$  with the machine longitudinal direction.

$$\therefore P_x = P_{xy} \cos (\frac{\pi}{2} - \phi) = P_{xy} \sin \phi$$



$$\text{and, } P_y = P_{xy} \cos \phi.$$

The detail observations are presented in a table in the next page,



## OBSERVATION TABLE :-

Serial no.	Spindle Speed ( <del>1147</del> ) (rpm)	cutting velocity (m/min)	Feed (mm/rev)	$P_{xy}$ (N)	$P_z$ (N)	$\xi$	$P_x$ (N)	$P_y$ (N)	$T_s$ (N/mm <sup>2</sup> )
1.	190	cutting velocity remains unchanged	0.08	232.6	543.8	2.6	224.7	60.2	972.5
2.	190		0.12	290.2	706.2	2.5	280.3	75.1	866.7
3.	190		0.16	336.5	856.2	2.4	325.0	87.1	812.1
4.	190		0.20	400.5	1043.8	2.35	386.9	103.7	804.2
5.	113	57	feed remains unchanged	310.1	725	2.6	299.5	80.3	864.4
6.	147	76		298.9	712.6	2.55	288.7	77.4	861.9
7.	190	96		292.8	712.8	2.5	282.8	75.8	874.8
8.	247	125		289.1	719	2.45	279.2	74.8	895.6



Variation of main cutting force with feed and cutting velocity' ①





# Variation of longitudinal force with feed and cutting velocity



shear stress with feed and cutting velocity



Variation of chip reduction coefficient with feed and cutting velocity





## DISCUSSION: =&gt;

① Explain the nature of variation in the graphs.

⇒ ① main cutting force or tangential force ( $P_z$ ) increases with the increase in feed and decrease with the increase in cutting velocity. It happens because,

$$P_z = t \cdot s \cdot \tau_s (\xi - \tan \gamma_0 + 1).$$

As the other parameters including cutting velocity are constant and hence  $P_z$  increases almost linearly with feed.

With increase in cutting velocity  $P_z$  decreases slightly because  $\xi$  decreases with increase in  $v_c$  and  $\tau_s$  decreases (very small) with increase in  $v_c$ .

$$\begin{aligned} \text{ii) } P_x &= P_z \cdot y \cdot \sin \phi \\ &= \frac{P_z (\xi - \tan \gamma_0 - 1)}{(\xi - \tan \gamma_0 + 1)} \sin \phi. \end{aligned}$$


hence,  $P_x$  is a function of 3 parameters, i.e.  $P_z$  &  $\xi$ . and  $P_x$  thus increases or decreases as the same reason as earlier one.

iii)  $\tau_s$  is a function of  $P_z$ ,  $s$  and  $\xi$ ;  $\tau_s = \frac{P_z}{t \cdot s (\xi - \tan \gamma_0 + 1)}$   
as,  $s$  increases,  $\tau_s$  decreases,  
as,  $v_c$  increases  $\xi$  decreases and  $P_z$  almost remains constant.

iv)  $\xi$  first increases and then decreases with increase in  $s$  and  $v_c$ , because,  $\xi = e^{\mu \left( \frac{\pi}{2} - \gamma_{\text{dyn}} \right)}$   
and,  $\xi = \cos \gamma \cot \beta + \xi \sin \gamma$ .

DATE . . .

SHEET NO. 6



$\xi$  is a function of  $\beta$  that means shear angle and  $\gamma_{dyn}$  and hence  $\xi$  is related to the formation of builtup edge. Beyond the builtup edge  $\xi$  decreases with the increase in  $s$  and  $v_c$ . We operate in such feed and cutting velocity range.

② Determine the ratio of main cutting force to feed force. Why it is more than 1?

①

Observations:	1	2	3	4	5	6	7	8
main cutting force ( $P_z$ ):	543.8	706.2	856.2	1043.8	725	712.6	712.8	719
feed force ( $P_{fy}$ ):	232.6	290.2	336.5	400.5	310.1	298.9	292.8	289.1
ratio ( $\frac{P_z}{P_{fy}}$ ):	2.338	2.433	2.544	2.606	2.337	2.384	2.434	2.487
	$s$ increases $\rightarrow$ ( $v_c$ const)				$v_c$ increases $\rightarrow$ ( $s$ constant)			

②  $P_z$  is the main cutting force because it is directly related to the power of the machining which is due to the turning of the work-piece whereas,  $P_{fy}$  comes due to the feed given to the tool. Cutting velocity is higher than feed in turning and hence  $P_z$  is greater than  $P_{fy}$ .

⑥ For orthogonal cutting,

$$\frac{P_z}{P_{xy}} = \frac{\xi - \tan^2 \alpha + 1}{\xi - \tan^2 \alpha - 1}$$

from this expression also we can suggest that,  
 $P_z$  must be greater than  $P_{xy}$ ;  $P_z > P_{xy}$

and hence,  $\frac{P_z}{P_{xy}} > 1$ .